



000025214

SCOPE FOR POND SEDIMENT CONTROL

REMOVAL OF SEDIMENT BUILD UP (PONDS A-4, B-5, AND C-2)

Prepared for:

FACILITIES ENGINEERING DEPARTMENT
Rocky Flats Plant
North American Space Operations
Rockwell International

Authorization No. 492065

January, 1989

Prepared by:

MERRICK & COMPANY 10855 E. Bethany Drive P.O. Box 22026 Denver, Colorado 80222

Best Available Copy

Reviewed for Classification

By: Wenny M. War

Date: 20 /989

ADMIN RECCRD

Page i

TABLE OF CONTENTS

		PAGE
I.	INTRODUCTION	1
II.	SOLUTION	1
III.	RECOMMENDATIONS	1
IV.	SOLUTION ORGANIZATION	1
	Construction Preparation	1
	Removal	1
	Installation	1
	Post Construction	2
v.	NOTES AND ASSUMPTIONS	2
VI.	APPENDIX A (Sketches)	
	Topographical Site Plan	
٧.	APPENDIX B (Cost Estimate)	
	Engineering Estimate	
	Construction Cost Estimate	

I. INTRODUCTION

This Scope and Estimate evaluated the requirements for the removal of the sediments from ponds A-4, B-5 and C-2 as a routine maintenance function. The requirement for the periodic removal of sediments from Surface Water Control Ponds is a condition of the National Pollution Discharge Elimination System (NPDES) permit. As these ponds are the last retention facilities on their various drainage basins, the removal of these sediments will allow the pond systems to be properly operated with no release of settleable sediment particles.

II. SOLUTION

Perform dredging activities to reduce sediment build up in ponds A-4, B-5, and C-2. Dredging limits will approximately coincide with the original pond bottom configuration.

III. RECOMMENDATIONS

- A. Expedite design and implementation of sediment removal to minimize the chances of an NPDES violation and maximize available sediment storage volume.
- B. Lower pond water levels as far in advance of the dredging as is practical from an operation viewpoint.

IV. SOLUTION ORGANIZATION

A. Construction Preparation

- 1. Draw down existing pond water levels as far as possible.
- Construct and/or install cofferdams, or bypass and diversion facilities at upstream end of pond.
- 3. Construct access roads and dewatering areas.

B. Removals

- Remove accumulated sediments from the ponds.
 - a) Remove sediments to original ground lines.
 - b) Dewater sediments.
 - c) Load and haul away for disposal at the designated site.

C. Installation

1. Coordinate the installation of bank stabilization measures with sediment removal to maintain bank stability for ponds A-4 and B-5.

D. Post Construction

- 1. Regrade site to blend into existing contours. Leave access roads for future maintenance of the ponds.
- Place topsoil and revegetate disturbed areas.

V. NOTES AND ASSUMPTIONS


- A. Sediment probes should be accomplished as a part of a geotechnical investigation to determine removal volumes. This Scope and Estimate assumes between 6 and 7 percent of the existing spillway volume to be the sediment volumes. It should be noted that the cost estimate is only moderately sensitive to changes in the volumes of sediment to be removed.
- Geotechnical investigations should be performed to determine if the removal of sediment will contribute ţο instability. This Scope and Estimate assumes that installation of bank stabilization measures will be required for ponds A-4 and B-5. This assumption is based on the reference to numerous slope failures within the pond basins in a Conceptual Design Report (CDR) prepared by Merrick & Company and Woodward-Clyde Consultants. The CDR was prepared to obtain funding for the removal of sediments from ponds upstream of those discussed in this Scope and Estimate. geotechnical investigation should also determine a drawdown rate which will not contribute to bank instability.
- C. Engineering will include the design and preparation of construction bid documents for the dewatering system, sediment removal from the ponds, further dewatering of removed sediments, haul roads and hauling for disposal, and restoring the work area at the close of the project.
- D. The work should be performed during the dry months of the year to limit the amount of stream flow that must be addressed by cofferdamming, piping and pumping.
- The dewatering of pond A-4 can be accomplished by drawing down Ε. the levels in pond A-3 prior to construction and using this pond as the upstream cofferdam. This can be done since releases to pond A-4 are controlled at pond A-3. Pond B-5 and C-2 will require the construction of an upstream cofferdam since controls similar to the A-series ponds do not exist. It is assumed that the cofferdams can be constructed from materials within the immediate area of the pond. That is to say that materials will not have to be imported for this purpose. Water will be pumped from the cofferdam at B-5 over the hill to the A-4 pond. Pumping from pond C-2 cofferdam to pond B-5 is included in the estimate in order to allow for the sampling of detained waters before release downstream. Pumping from pond A-3 to the B-series ponds for work on the A-4 pond may not be required if the work is accomplished during the dryer months of the year. The capacity of pond A-3

should be sufficient to impound stream flows for the duration of the construction on pond A-4. It should be noted that considerable cost savings may be achieved by combining the work under this Scope and Estimate with that of reconstructing the outlet works of the ponds. The dewatering and access road construction could be accomplished once for both projects.


- F. Stabilized access roads will be constructed around each of the ponds to allow for the movement of excavation equipment and hauling of removed sediments. Gravel base materials have been estimated, however, other stabilization techniques should be considered during design.
- G. The sizing of the cofferdams and pumping systems assumes that a failure of the cofferdam in an unusually heavy precipitation event during the construction effort will have no major effect beyond inundating the construction area and related setbacks. Sufficient time should be available to remove construction equipment from the pond basin in anticipation of a cofferdam failure. Repeating the dewatering effort and cleaning up the work area will be required should this event occur. A cofferdam failure would not release water down stream of the plant site since the existing dam and outlet work controls will remain operable throughout the duration of the work.
- H. The estimate is based on removal of sediments by means of a drag line and hydraulic excavator, each handling approximately 50% of the sediments removed from the ponds. Consideration should be given to other methods during the initial design stages.
- I. The estimate assumes that the slope stabilization performed the on.pond B-5 embankments in 1984 does not eliminate the potential for future slides in this basin. Stabilization is assumed to be required for work within ponds A-4 and B-5. Pond C-2 is in a basin assumed to have more gradual and stable The estimate does not include slope embankment slopes. stabilization for this pond. These assumptions will have to be confirmed by a geotechnical analysis during the design. Instrumentation to monitor movement may be required for the hills above each of the ponds to minimize the potential for slope failure. Instrumentation is estimated only for ponds A-4 and B-5. If movement is detected, work will be stopped and efforts to stabilize the slope should be undertaken.
- J. Removed sediments will be land filled on the RFP within a 6 mile round trip haul distance from the ponds.
- K. Sediments removed from the ponds will be windrowed near the pond to allow drainage before loading into trucks for hauling to the fill area. Windrows should be placed so that drainage does not effect the work area.

- L. All disturbed areas at the work site will be regraded to blend with natural contours and reseeded for erosion control and slope stability. Access roads will be left in place for future maintenance work on the ponds.
- M. No improvements will be made on existing access roads.
- N. Radiation monitoring, soil sampling and laboratory analysis will be performed on pond sediments to detect contamination. The estimate assumes that no contaminants will be found. However, it is assumed that the monitoring program will be required to demonstrate that contaminants do not exist.


APPENDIX A




DIAN VIEW - I'II A



ZU MAU OI MAI VIEW



DAH BS PROLESEC COFFER LAM LOCATION



APPENDIX B

Engineer Inspecti of Const Removal	ing, Design and interpretation at approximately 26 % cruction and Costs	•		\$181 , 772
	Title I, II, & III - Design Inapection			
Construc	tion Costs			≉a99,192
	Improvements to Land	DAM A4 DAM B5	\$264,897 \$264,050 *155,540	
	New Buildings			
	Building Medifications			
	Other Structures			
	Special Facilities			
	Utilitias			
	Project and Schetruction Management			
	Standard Equipment			
Pemoval	Cost Lasa Salvaga			
Continge of all s	ency Allowance Gapproximately 28 other costs	5 %		÷228,863
TOTAL PR	ROJECT COST			\$1,109,817
7-18 885 Engineer MCN7-275	timate was prepared by Rockwell Inter ting Department based on Conceptual ! EAR:	rnational Sesign Fe	. Facilities Sort.	

POND SEDIMENT CONTROL

MANHOUR RECAP

PROJECT DISCIPLINE	TITLE I HOURS	TITLE II HOURS	TITLE III HOURS	TOTAL HOURS	RATE (\$/HR)	TOTAL COST (\$)
PROJECT MANAGER	31	46	16	93	\$26.44	\$2,459
ARCHITECT	0	0	0	0	\$16.47	\$0
STRUCTURAL ENGINEER	0	0	0	0	\$16.92	\$0
MECHANICAL ENGINEER	0	0	0	0	\$21.67	\$0
ELECTRICAL ENGINEER	0	0	0	0	\$22.19	\$0
CIVIL ENGINEER	208	262	224	694	\$19.44	\$13,491
SURVEYOR	216	0	0	216	\$12.21	\$2,637
TECHNICIAN	0	46	36	82	\$14.18	\$1,163
CAD DRAFTER	120	100	24	244	\$10.96	\$2,674
TYPIST	32	28	26	86	\$9.57	\$823
TOTAL DIRECT LABOR	607	482	326	1415		\$23,248
OVERHEAD & 6.A. (103.021)						\$23,950
TOTAL LABOR COST						\$47,197
TOTAL MATERIAL COST						\$1,870
TOTAL TRAVEL COST						\$756
TOTAL OTHER COSTS (LIST):	GEOTECHNICAL LAB ANALYSIS=	CONSULTANTS= \$7,500 \$60,000	SLOPE	MONITORING= \$41,	100	\$108,600
CLOSE-OUT COST	END MMME/313-	***************************************				\$316
TOTAL COST						\$158,740
FIXED FEE (8.5%)				·		\$13,493
CPFF						\$172,232

PROJECT: POND SEDIMENT CONTROL		•	CON	TRACTOR:	MERRICK & CO	MPANY / Architects and En	gineers
CONTRACT:				IMATE BY:	B. KRULL		
A. DRAWING LIST	· TI		TIT	LE II	INDEX OF DRAI	WINGS: SHEET TITLE	
1. TITLE SHEET	(3)	(3)			
2. LOCATION PLAN	(t				
3. LEGEND AND SYMBOLS	(3)	(3)			
4. DEMOLITION	(}	()			
5. P & ID'S							
new -	()	()			
revised -	(}	()			
6. ARCHITECTURAL							
new -	(,	()			
revised - 7. CIVIL/STRUCTURAL	(1	,	,	(7)	ADEA DIANC	
new -	1	14 1	(3)		AREA PLANS PLAN SHEETS	
revised -	1	17 /	(14)		TYPICAL SECTION	
B. HECHANICAL/UTILITIES	1	,	,	17 /		COFFER DAM	
new -	1)	()		DETAIL SHEET-TITLE II	
revised -	ì	ì	i	,	(0)	SCHILL WILL HILL H	
9. ELECTRICAL		·	·	•	*(3)	INDEPENDANT PACKAGES"	
new -	(}	(}			
revised -	()	()			
10. INSTRUMENTATION							
new -	()	(}			
revised -	1)	(}			
11. OTHER							
NEW -	()	()			
revised -) 	()			
TOTAL		23		26			
B. MATERIAL COST		 TLE	111	 LE II	BID PKG	cost	TOTAL
		sets		sets	# sets	per sht	COST
1. SPECS:# pgs= 150		5		5	25	\$0.10	\$525. 00
2. HYLARS		2		2		\$3.64	\$356.72
3. BLUEPRINTS		5		5	25	\$0.42	\$375.90
4. REDUCED COPIES		5		5	5	\$0.30	\$112.50
5. MISC MAT'LS (LIST):						LUMP SUM	\$500.00
***************************************						TOTAL===>	\$1,870.12
C. TRAVEL COST		TLE I				MILEAGE CHG	TOTAL
					# trips		COST
1. PLANT SITE(80 miles)		12		4	29	\$0.21	\$756.00
2. MISC: miles= 0.00				•		\$0.21	\$0.00
						TOTAL === >	\$756.00

D. TITLE I SERVICES	P.M.	ARCH	S.E.	M.E.	E.E.	C.E.	SURVEY	TECH	CAD	W.P.	SUBTOTAL
1. DRAWINGS	4					16			120	4	144
2. DESIGN	4		:			80					84
3. DESIGN SUMMARY	2					24					26
4. BACKUP INFORMATION	-					8	216				224
5. BUTLINE SPECIFICATION	2					12				16	30
6. PROJECT SCHEDULE	1					4					5
7. CONSTRUCTION ESTIMATE	2					8					10
8. QUALITY ASSURANCE	8					24					32
9. CONF./CORRESPONDENCE	4					16				8	28
10. ONSITE - KICKOFF MTG	4					4				2	10
- DATA COLL	•					Ŕ				-	8
- TITLE I REV						4				2	6
		۸					 34/		170		
TITLE I SUBTOTAL======>	3i	0	0	-	0	208	216 	0	120	32 	607
. TITLE II SERVICES	P.M.	ARCH	S.E.	M.E.	E.E.	C.E.	SURVEY	TECH	CAD	W.P.	SUBTOTAL
1. DRAWINGS	4					20			100	4	128
2. DESIGN	8					120					128
3. BACKUP INFORMATION											0
4. SPECS CONSTRUCTION	4					16		15		8	144
- G.F.E.											0
5. PROJECT SCHEDULE	4					4		2			10
6. CONSTRUCTION ESTIMATE	4					16		16			36
7. QUALITY ASSURANCE	4					24					28
8. CONF./CORRESPONDENCE	8					16				8	32
9. DNSITE - DATA COLL.						16					16
- TITLE II REV	4					6		6		4	20
- PRE-BID CONF	•					4		4		•	
10. TECHNICAL EVALUATIONS	4					Я		•		7	14
11. ADDENDA	•					8				2	10
12. BID ESTIMATE	2					Ā		2		-	g
12. DIA COLLUNIC											
TITLE II SUBTOTAL=====>	46	0	0	0	0	262 	0	46	100	28 	582
. TITLE III SERVICES	P.M.	ARCH	S.E.	M.E.	E.E.	C.E.	SURVEY	TECH	CAD	W.P.	SUBTOTAL
1. APPROVE VENDOR SUBM						4					4
2. VENDOR INSPECTIONS											0
3. MODIFICATIONS	4					32				8	44
4. AS-BUILT DRAWINGS						4		36	24		64
5. CONSTRUCTION REPORTS	4					32				16	52
6. ONSITE - PRECNST CONF						8				2	10
- CONSTR. OBSV	8					120					128
- FIN WALKTHRU					•	24					24
TITLE III SUBTOTAL====>	16	0	0	0	0	224	0	36	24	26	326
TITLES I, II, & III====>	93	0	0	0	0	694	216	82	244	86	1515

POLICY & PROCEDURE - ECONOMIC ESCALATION RATES

Rockwell International

August 22, 1988

FISCAL YEAR	EQUIVALENT ANNUAL RATE (%)
1988	NA
1989	4.30
1990	4.55
1991	4.76
1992	4.97
199 3	5.14
1994	5.25

Formula for Calculating the E.M. (ESCALATION MULTIPLIER) Rates:

 $E.M. = (1 + i/12)^n$

Where:

i = Equivalent Annual Rate at Micopoint of Time Frame to (1.100).

n = # of Months Between Date of Cost Data and Midpoint of Time Frame.

CALCULATIONS:

Project: POND SEDIMENT CONTROL

Late: 27 JAN 89

COST DATA	i	f.	E.M.
ENGINEERING	N/A	₹	1,000
CONSTRUCTION	4.55	12	1.046
P % CM	4.55	10	1.039

User: KEN

<a31062>RDCKWELL>RDDF>COST>DAM>0_INSP6

Label: PRT005 -form L1/GRE

Pathname: <A31062>RUCKWELL>RUGF>COST>DAM>0_INSPS File last modified: 89-01-27,15:17:44,Fri

Spooled: 89-01-27,15:19:56.Fri [Spooler rev 19.1,] Started: 89-01-27,15:21:12.Fri on: AMLC by: PR1

GREEN TRACK , 132 columns, high-speed dot matrix

Page - 1	€ TOT		9, 120	9, 120	9, 540	\$9, 540 \$9, 540
	EQUIP FOTAL			o o	9120	0 0
-27-89	TOTAL LABOR COSTS		9120	9120 9540	9540 -	9540
Date: 01-27-89	LABOR LABOR RATE	7 1 1 1 1 1 1 1 1 1	38.00			
252-6761K1 FORM	TOTAL MAN HOURS		240.00	00.00		
INSPECTION Job No: 252-6761K1 COST ESTIMATE - LONG FORM	HOURSYUNIT		2. 000			
INSPECTION COST ES	MATERIAL MATERIAL TOTAL			0		00
DAM A4, B5, & C2	COST					
A4, B3	FIND		DAY			
DAM	QUANT UNIT		120 DAY	1. 046		
CONTROL			Ê	.		01400
POND SEDIMENT CONTROL	DESCRIPTION	DIVISION 1 SECTION 01400 QUALITY CONTROL	INSPECTION SUBTOTAL	Escalation	Labor Mark-up	TOTAL SECTION 01400 TOTAL DIVISION 1

\$9, 540	7.64		
0. \$9,540	ö		
Date: 01-27-89 9540	9540		
INSPECTION Job No. 252-6761K1 Date: 01-27-89			
INSPECTION	0		
DAM A4, B5, & C2			
POND SEDIMENT CONTROL DAM A4, 85, & C2 TOTAL DIVISION 1	PROJECT TOTAL		

2

/

User: KEN <A31062>ROCKWELL>RODF>COB#>DAM>O_PCMS

-at

按据表演者的事情是是有的表示的表示,我们是有有的,我们也是有的,我们也是有的,我们也是有的,我们也是有的,我们也是有的,我们也是有的,我们也是有的,我们也是有的,我们 这种的的,我们是是是是是是一种的,我们是是是一种的,我们是是一种的,我们是是一种的,我们是是一种的,我们是是一种的,我们是是一种的,我们是是一种的,我们是是一种的,我们

Label: PRT006 -form L1/GRE Pathname: CA31062>ROCKWELL>ROOF>COGT>DAM>0_PCMS File last modified: 89-01-27.15:18:08.Fri

Spooled: 89-01-27.15:20:44.Fri [Spooler rev 19.1.] Started: 89-01-27.15:22:04.Fri on: AMLC by: PRI

GREEN TRACK , 132 columns, high-speed dot matrix

Page - 1	11, 400	14, 136	14, 58)	\$14.687
Egu <u>i</u> Piuga Jinga	#	0 0	14136	o o
27-89 Tot <u>al La</u> bor	11400	14136	14687 -	14687
Date: 01-27-89 <u>LABOR</u> LABOR TOTA	98. 99.00 99.00	•		•
52-6761K1 FORM TOTAL	300.00	372.00		
INSPECTION Job No: 252-6761K1 COST ESTIMATE - LONG FORM ERIAL MAJERIAL LONG CHAIT	88.000 000 000	ł		
INSPECTION COST EST MATERIAL MATERIAL		00		0 0
ce Ce Ce Ce Ce Ce Ce Ce Ce Ce Ce Ce Ce Ce				
DAM A4, B5,	:s 150 DAY 9 DAY	1. 039		
POND SEDIMENT CONTROL	DIVISION 1 SECTION 01100 SPECIAL POLICY PROCEDURES PROJ ADMINISTRATOR (M) RADIATION MONITOR (RI)		k -up	SECTION 01100 DIVISION 1
POND SEDIMEN	DIVISION 1 SECTION 01100 SPECIAL POLICY PROCI PROJ ADMINISTRATOR RADIATION MONITOR	SUBTOTAL Escalation	Labor Mark-up	TOTAL SECTOTAL DIVI

	\$14, 687	\$14.007
	0.	ö
Date: 01-27-89	0 14687 0 \$14, 6	14687
Job No: 252-6761K1		
INSPECTION	0	o
DAM A4, B5, & C2		
POND SEDIMENT CONTROL DA	TOTAL DIVISION 1	PROJECT TOTAL

User: KEN

lat t

<A31062>RDCKWELL>RODF>COST>DAM>D_A4

在家中的一个,我们,我们的一个,我们的一个,我们的一个,我们的一个,我们的一个,我们的一个,我们的一个,我们的一个,我们的一个,我们的一个,我们的一个,我们的一个,我们

Label: PRT003 -form L1/GRE

Pathname: <a31062>ROCKWELL>RODF>COST>DAM>O_A4
File last modified: 89-01-27,15:25:00.Fri

Spooled: 89-01-27,15;26;12,Fri [Spooler rev 19.1,] Started: 89-01-27,15;26:12,Fri on: AMLC by: PRI

GREEN TRACK , 132 columns, high-speed dot matrix

POND SEDIMENT CONTROL	DAM A4	Job No: 25	12-6761K1 COST ES	Job No:252-6761K1 Date: 01-27-89 COST ESTIMATE - LONG FORM	-89 Form				Page - 1
		H	MATERIAL			LABOR		EQUIP	(°)
DESCRIPTION	GUANT UNIT	CDST	MATERIAL	HDURS/UNIT	TOTAL MAN HOURS	LABOR	TOTAL LABOR COSTS	EGUIP	TOTAL
DIVISION 1 SECTION 01050 CONSTRUCTION SURVEY									
CONSTRUCTION SURVEY (M)	5 ACRE	25.00	125	14, 540	72.70	14. 27	1037		1.162
SUBTOTAL			125		72. 70		1037	Ö	1,162
Maintenance Mark-Up 1 Overhead Profit Bond Escalation	1150 1150 1150 1150 1150 1150		151 155 166 176		88888 66666		1089 1252 1377 1381 1445	ರಕ್ ರಕರ	
Labor Mark-up Material Mark-up							1445 174	1037 125	408 49 1, 619
TOTAL SECTION 01050	ļ	•	174				1445	o	\$1,619
TOTAL DIVISION 1			174				1445	ó	\$17.619

POND SEDIMENT CONTROL	DAM A4	Job No: 25	No: 252-6761K1 COST ESI	Date: 01-27-89 ESTIMATE - LONG FORM	:89 FORM				Page - 2
		≨	MATERIAL			LABOR		EQUIP	
DESCRIPTION	QUANT UNIT	COST	MATERIAL TOTAL	HOURS/UNIT	TOTAL MAN HOURS	LABOR	TOTAL LABOR COSTS	EQUIP TOTAL	TOTAL
DIVISION 2 SECTION 02500 HAUL ROAD									
				0, 013 0, 007	4 0 8 4 0 0 0 0	19.44	885 350	1220.	1. 2.2.2.0 2.0.0.0.0.0.0.0.0.0.0.0.0.0.0.
12 " PIT RUN (H) OPERATOR (H) LABORER (H)	00000	4. 50	11700	0.007			354 148	405.	12, 12, 12, 12, 13, 14, 14, 14, 14, 14, 14, 14, 14, 14, 14
				0.044	114, 40	21. 78	2492		400 400 400 400
	2000	9	Ċ	0 004	10. 4 0 5. 20	19.44	202	165.	2002 745
OPERATOR (H)		70.7	\$ 2 7	0.029 0.118	0. B7 3. 54	19. 44	17 51	4 .	338 172 117
	388	;	č	0. 001 0. 001	11. 90	19.44	214	660.	214 157
		20.11	or i	0.154	1.83	19.44	36	35.	171
SUBTOTAL			12160		256.86		4980	5304.	£5;
Maintenance Mark-Up 1 Overhead 1 Profit 1 Bond Escalation 1	1. 050 1. 150 1. 003 1. 046		12768 14683 16131 16199 16944		00000 00000		5229 6013 6614 6634 6939	5569. 6405. 7045. 7391.)
Labor Mark-up Material Mark-up Equipment Mark-up							6939 16944 7391	4980 12160 5304	1, 959 4, 784 2, 087 31, 274
TOTAL SECTION 02500		ŧ	16944			1	6669	7391.	\$31.274

***_(*)

Pate: 01-27-89 Pate: 01-27-89 Pate: 01-27-89 Pate: 01-27-89 Pate: 0.027 Pate: 0.027 Pate: 0.028 Pa
MATERIAL HOURS/UNIT MAN HOURS RATTOR 19. 0.029 153.70 19. 0.029 19. 0.029 19. 0.029 19. 0.029 19. 0.029 19. 0.029 19. 0.029 19. 0.029 19. 0.029 19. 0.029 19. 0.029 19. 0.029 19. 0.029 19. 0.029
252-6761K1 Date: 01-27-8 MATERIAL MANIT TOTAL HOURS/UNIT 0.029 0.029 0.029 0.029 0.029
MATERIAL HOURS/ TOTAL HOURS/ 0.00
MATERIAL MATERIAL TOTAL
LIND COST
60 CY
DESCRIPTION DIVISION 2 SECTION 02770 SEDIMENT REMOVAL POND TO WINDROW (M) OPERATOR (M) HYDRERATOR (M) HYDRAULIC EXCAVATOR (M) OPERATOR (M) HYDRAULIC EXCAVATOR (M) OPERATOR (M)

	\$1.619	\$263.	\$264,897
	Ö	81984.	81984.
	1445	91477	61262
Date: 01-27-89			
Job No: 252-6761K1	174	91477	91651
DAM A4			
POND SEDIMENT CONTROL	TOTAL DIVISION 1	TOTAL DIVISION 2	PROJECT TOTAL

User: KEN

-at

<a31062>ROCKWELL>ROOF>COST>DAM>0_B5

Label: PRT003 -form L1/GRE

Pathname: <a31062>ROCKWELL>ROGF>COST>DAM>0_B5
File last modified: 89-01-27.15:16:16:16.Fri
Spooled: 89-01-27.15:21:36.Fri
Started: 89-01-27.15:21:40.Fri
on: AMLC by: PRI

GREEN TRACK , 132 columns, high-speed dot matrix

W

POND SEDIMENT CONTROL	DAM B5	Job No: 252-676	51K1	Date: 01-27-89 ESTIMATE - LONG FORM	-89 Form				Page - 1
		E	MATERIAL			LABOR		EGUIP	<i>(</i>
DESCRIPTION	GUANT UNIT	COST	MATERIAL TOTAL	HOURS/UNIT	TOTAL MAN HOURS	LABOR	TOTAL LABOR COSTS	FOUIP	TOTAL
DIVISION 1 SECTION 01050 CONSTRUCTION SURVEY									
CONSTRUCTION SURVEY (M)	M) 3 ACRE	25.00	75	14.540	43. 62	14. 27	229		769
SUBTOTAL			75		43. 62		622	ö	697
Maintenance Mark-Up Overhead Profit Bond	1. 050 1. 150 1. 1003		74 1000 1000 1000		88888 66666		653 751 826 828	ರರರರ	
Escalation	1. 046		103		o o		9	<i>;</i>	/
Labor Mark-up Material Mark-up							866 - 105 -	622 75	444
TOTAL SECTION 01050		•	105				846	Ö	1268
TOTAL DIVISION 1			105				998	ο̈́:	176\$
)

ķ

- -

:

POND SEDIMENT CONTROL	DAM B5	Job No: 252	52-6761K1 Date: COST ESTIMATE	Date: 01-27-89 HIMATE - LONG FORM	-89 FORM				Page -
			MATERIAL	:		LABOR		EQUIP	
DESCRIPTION DIVISION 2 SECTION 22 THE COFFER DAM	QUANT UNIT	1803	TOTAL	HOURS/UNIT	MAN HOURS	RATE	COSTS	TOTAL	TOTAL
	1250	4. 50	5625	0 007	g 1		170	338.	5, 96
LABORER (M)	1200			0.007	00	14, 27	71	8000	7.00
	1010 1010 1010 1010 1010 1010 1010 101			0.044	55.00	21, 78	1198	- AB	10-c
	000			0.004 0.002	oon rici	19, 44	36	j S	10° C.
OPERATOR (M) LABORER (M)	300 DAY 300 DAY 300 DAY			2.000			1166 428	1140.	1, 140 1, 166 428
SUBTOTAL		•	5625		166. 25		3166	3954.	12,745
Maintenance Mark-Up 1 Dvarhead Profit Bond Escalation 1	1. 050 1. 150 1. 003 1. 046		5906 6792 7471 7493 7838		888 88 66666		3324 3823 4203 4218 4412	4152 4774 5252 5252 5510	
Labor Mark-up Material Mark-up Equipment Mark-up							4412 - 7838 - 5510 -	3166 3625 3954	2, 2, 2, 2, 3, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4,
TOTAL SECTION 02170		,	7838				4412	5510.	\$17,759

POND SEDIMENT CONTROL		DAM B5	Job No: 252-67	61K1 C0ST	Date: 01-27-89 ESTIMATE - LONG FORM	-89 Form				Page - 3
			T T	MATERIAL			LABOR		EGUIP	6
DESCRIPTION	ð	GUANT UNIT	COST	MATERIAL TOTAL	MAN HOURS/UNIT	TOTAL MAN HOURS	LABOR	TOTAL LABOR	EGUIP	TOTAL
DIVISION 2 SECTION 02500 HAUL ROAD										-
CAVATION DPERATOR ABORER					0.013	32. 50 17. 50	19, 44	632 250	1220.	1, 220 632 232 250
12 " PIT RUN (M) OPERATOR (M) LABORER (M)		1900 CY 1900 CY	4.50	B550	0.007	13.30	19.44 14.27	259 108	405.	8, 955 1955 1009 1009
					0.044	83. 60	21. 78	1821	2803.	
			6	Č	0.004	7. 60 3. 80	19, 44	148 54		### ((주변)
OPERATOR (A	•	3888 3888	10.74	124	0. 029 0. 118	0.87 3.54	19. 44 14. 27	17 51		138 17 18
				Ċ	0.001	11. 90	19.44	214	j w	2000 1314
	ÊÊ	IZ MSF	05 .1	1.36	0.154	1.85	19, 44	36	35.	36
SUBTOTAL				9010		194, 16		3747	5304.	18.
Maintenance Mark-Up Gverhead Profit Bond Escalation	54456	050 150 003 046		9460 10879 11967 12003 12555		00000 00000 00000		3934 4524 4976 4991 5221	5569. 6405. 7045. 7391.	
Labor Mark-up Material Mark-up Equipment Mark-up								5221 - 12555 - 7391 -	3747 9010 5304	1, 474 3, 545 2, 087 25, 167
TOTAL SECTION 02500				12555			ı	5221	7391.	\$25, 167

POND SEDIMENT CONTROL	DAM B5	Job No: 252-	6761K1 COST	Date: 01-27-89 ESTIMATE - LONG FORM	-89 FORM				Page - 4
		귎	MATERIAL			LABOR		EQUIP	(
DESCRIPTION	GUANT UNIT	COST	MATERIAL	MAN HOURS/UNIT	TOTAL MAN HOURS	LABOR RATE	TOTAL LABOR	EQUIP	TOTAL
DIVISION 2 SECTION 02770 SEDIMENT REMOVAL									
POWD TO WINDROW	(
OPERATOR (M)	JOOG			0. 029 0. 028	124. 70 120. 40	19, 44 14, 27	2424 1718	5499.	5, 499 2, 424 1, 718
OPERATOR (M) OILER (M) ERONT END LOADER (M)	2000 0000 0000 0000 0000 0000			0.029	124. 70	19.44	2424	7644.	7,644 2,424 1,718
LABORER (%)				0.011	94. 60 43. 00	19.44	1839 614	4056.	4,056 1,839 614
LABORER (M)	DAY DAY			8. 000 4. 000	16. 00 B. 00	19. 44	311	1426.	1, 426 311
AMSTER				0.044	378.40	21. 78	8242	14586.	14, 586 8, 242
	PAY PAY PAY			2. 000 1. 000	22.00 11.00	19. 44	428 157	935 935	6.44 6.08 7.0 7.0
FRONT END LOADER (M) OPERATOR (M) LABORER (M)	8600 CY 8600 CY			0.001 0.003	94. 60 43. 00	19. 44 14. 27	1839	4056.	11,056
			708	0.044	37B. 40	21, 78	8242	14586.	14. 0.00 0.000 0.000
OPERATOR (M) EROSION CONTROL (A)	43 MSF 10600 CV	i n	485 53000	0.154	6. 62	19, 44	129	124.	6±0 129
				0.140	1484, 00	14, 27	21177		21, 177
SUBTOTAL			53486		3069, 82		21990	52509.	157, 985
Maintenance Mark-Up 1 Uverhead 1 Profit Bond Escalation 1	150 150 003 043		56160 64584 71042 71255 74533		00000		34589 62777 69055 69262 72448	55134. 63405. 69745. 69954. 73172.	
Labor Mark-up Material Mark-up Equipment Mark-up	ļ	·				,	72448 74533 73172	51990 53486 52509	20, 458 21, 047 20, 663 220, 153
TOTAL SECTION 02770			74533			·	72448	73172.	\$220,153
TOTAL DIVISION 2			94926				82081	86072.	\$263,079

:	126\$	\$263.	\$264,050
	o	86072.	86072.
	998	94926	82947
Date: 01-27-89		h was and and and and and was one in the face of the total and and the face who does the	
Job No: 252-6761K1	105	94926	95031
DAM B5			
POND SEDIMENT CONTROL	TOTAL DIVISION 1	TOTAL DIVISION 2	PROJECT TOTAL

User: KEN

-at

<A31062>ROCKWELL>RODF>CDST>DAM>0_C2

 Label: PRT004 -form L1/GRE

Pathname: <a31062>ROCKWELL>ROOF>COST>DAM>0_C2 File last modified: B9-01-27.15:17:04.Fri Spooled: B9-01-27.15:19:24.Fri Spooler rev 19.1.3 Started: B9-01-27.15:21:24.Fri on: AMLC by: PRi

GREEN TRACK , 132 columns, high-speed dot matrix

POND SEDIMENT CONTROL	DAM C2	Job No: 25	Job No: 252-6761K1 Bate: COST ESTIMATE	Date: 01-27-89 TIMATE : LONG FORM	-89 FORM				Page - 1
DESCRIPTION	QUANT UNIT	LANT	MATERIAL MATERIAL TOTAL	MAN HDURS/UNIT	TOTAL MAN HOURS	LABOR LABOR RATE	TOTAL LABOR COSTS	EQUIP EQUIP TOTAL	TOIAL
DIVISION 1 SECTION 01050 CONSTRUCTION SURVEY CONSTRUCTION SURVEY (M)	9 ACRE	25.00	10 01 01	14, 540	130,86	14. 27	1867		2,092
SUBTOTAL		•	225		130.86		1867	ó	2, 092
 Maintenance Mark-Up Overhead Profit Bond Escalation	1. 150 1. 150 1. 003 1. 046		9358116 9358116		68688 66666		1960 2255 22474 2474 2600	ರ ರರರ ರ	
Labor Mark-up Material Mark-up							2600 - 313 -	1867 225	733 88 87 2, 913
TOTAL SECTION 01050		t	313				5600	ó	\$2,913
TOTAL DIVISION 1			313				2600	0	\$2,913
									-

Job No:252-6761%1 Date: 01-27-89 COST ESTIMATE - LONG FORM MATERIAL
TERIAL MOURS/UNIT
5625
Ö
dd
51.1
5625
5906 6792 7471 7493 7838
7838

POND SEDIMENT CONTROL	DAM C2	Job No: 252-67	61K1 COST	Date: 01-27-89 ESTIMATE - LONG FORM	-89 Form				Page 1 3
DESCRIPTION	QUANT UNIT	COST	MATERIAL MATERIAL TOTAL	MAN HOURS/UNIT	TOTAL MAN HOURS	LABOR LABOR RATE	TOTAL LABOR COSTS	EGUIP EGUIP TOTAL	\ (
DIVISION 2 SECTION 02500 HAUL ROAD							4 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
EXCAVATION (F	2000 CY 2000 CY 2000 CY	4 4	V96.7	0.013	26. 00 14. 00	19. 44 14. 27	505 200	1220.	11.200
OPERATOR (M)	0000		06/0	0.007	10.50 6.00	19.44	204 86	405.	7, 13 204 80
	200			0.044	99.00	21. 78	1437	2805.	1, 80
	2000	92.00	60	0.004	3. 3. 3.	19.44	117	165.	3-4
	8888		1	0. 029 0. 118	3. 87 547	19. 44	1.7 51	4.	33.1
LABORER (#	000		Ċ	0. 001 0. 001	11: 00	19. 44	214	.099	244 244 244 244
		00.11	136	0.154	1.85	19.44	36	35.	7.6
SUBTOTAL			7210		159.76		3067	5304.	15,
Maintenance Mark-Up Overhead Profit Bond Escalation	1. 050 1. 150 1. 000 1. 046		7570 8706 9577 9606 10048		88888 66666		3220 3703 4073 4273	5569. 6405. 7045. 7391.)
Labor Mark-up Material Mark-up Equipment Mark-up							4273 - 10048 - 7391 -	3067 7210 5304	1, 206 2, 838 2, 087 21, 712
TOTAL SECTION 02500		•	10048			'	4273	7391.	\$21.712

POND SEDIMENT CONTROL	DAM C2	Joh No.2	No. 252-6761K1 COST ES	Bate: 01-27-89 ESTIMATE - LONG FORM	-89 FORM				Page - 4
		E	MATERIAL			LABOR		EGUIP	
DESCRIPTION	GUANT UNIT	TINO	MATERIAL	HDURS/UNIT	TOTAL MAN HOURS	LABOR	TOTAL LABOR	EGUIP	TOTAL
DIVISION 2 SECTION 02770 SEDIMENT REMOVAL									
POND TO WINDROW (M) DRAGLINE (M)	3900							5400	7
OPERATOR (M) OILER (M)	2000			0, 029 0, 028	113, 10	19, 44 14, 27	2199 1558		1, 55B
OPERATOR (M) OILER TON LOADER (M)	2000 2000 2000 2000 2000 2000 2000 200			0.029 0.028	113.10	19. 44 14. 27	2199 1558	7044.	7, 044 1, 1994
OPERATOR (M)				0. 011 0. 005	85. 80 39. 00	19. 44	1668 557	4006.	1. 6.00 1. 6.00 1. 6.00 1. 6.00
OPERATOR (M) LABORER (M)	, , , , , , ,			B. 000 4. 000	16. 00 8. 00	19. 44	311	1426.	1, 426 311 114
HAUL FAMSTER (N)	00E/			0.044	343, 20	21.78	7475	14586.	14, 586 7, 475
	44			2. 000 1. 000	28.00 14.00	19. 44 14. 27	200	9	1000 140 140
FANT END LOADER (H) OPERATOR (H) LABORER (H)	7800 CY 7800 CY			0 011	85. 80 39. 00	19. 44	1668	4056.	() ()
	7800		Č	0, 044	343, 20	21.78	7475	14586.	14, 586 7, 475
OPERATOR (M)	14	11.30	400	0.154	6. 62	19.44	129	164.	129
SUBTOTAL			486		1453, 22		28212	52509.	81.207
Maintenance Mark-Up 1 Gverhead 1 Profit 1 Bond 1	0000 0000 046		510 587 646 648 678		00000 00000		29623 34066 37473 37385 39314	55134. 63403. 69745. 73172.	
Labor Mark-up Material Mark-up Equipment Mark-up							39314 678 73172	28212 486 52509	11, 102 192 20, 663 113, 164
TOTAL SECTION 02770			678				39314	73172.	\$113,164
TOTAL DIVISION 2			18564				47999	86072.	\$152, 635

TOTAL DIVISION 2 TOTAL DIVISION 2 PROJECT TOTAL	POND SEDIMENT CONTROL DAM C2 Job N	Job No: 252-6761K1	Date	Date: 01-27-89			-
TAL DIVISION 2 18564 0JECT TOTAL	1	313					-
DJECT TOTAL	O.	<u>u</u>			2600	Ö	\$2, 913
				47999 86072. \$152.	47999	86072.	\$152.
		18877			50599	86072.	\$155, 548

CONTINGENCY ANALYSIS SUMMARY (CSI FORMAT)

AUTHORIZATION NO.:

PROJECT TITLE: POND SEDIMENT CONTROL

: STATION: BED

LDIATION: REP			
CONTINGENCY RA	NGE & MIDPOINTS		
	II (5% - 15%)	10%	
CONCEPTUAL (15% - 25%) 20% OWE-F	P/MTC (5% - 10%)	7.5%	
TITLE I (10% - 20%) 15% CWE-C	99F (10% -15%)	12.5%	
ELEMENT OF COST/OSI DIVISION	COST	CONTINGENCY	
=======================================	; ====================================	PERCENT 	DCLLARS
ENGINEERING (TITLE I.II,II) CONSTRUCTION INSPECTION CONSTRUCTION & PROJECT MANAGEMENT	172,232 9,540 14,637	25 % 25 % 25 %	\$43.053 \$2,365 \$3,672
1. GENERAL REQUIREMENTS	5. 503	28 %	\$1,513
2. SITEWORK	678,992	26 %	\$178 .235
3. CONCRETE	; ;	0 %	\$ 0
4. mABONRY	1	0.5	\$ €
E. METALE		- a.	7
e WG3D & PLASTICS		0.7	\$ (
7. THERMAL & MOISTURE PROTECTION	; ; ;	0 %	\$ 0
3. DOORS & WINDOWS		0 %	\$ (
7. FINISHES	: : :		\$.
10. SPECIALTIES	: : : :	0 %	\$ \$
11. BBCIRMENT			五.1
II. FURNISHINGS		5.5	\$.7
13. SPECIAL CONSTRUCTION	: :	2 %	\$ (
14. COMUSAINS SYSTEM			a (
15. MECHANIJAL		0.14	\$ ↓
16. ELEITFICAL		0 %	李 〇 :
	 		: :
TOTAL	980,9 5 4	24 %	\$228,563 ¹
ANALYSTS SESSENCE SY			
ANALYSIS PERFORMED BY:			
FEVIEWED BY PE:			
REVIEWED BY PA:			
APERITYED BY DE MANAGER:		일위(E:	

Α.	DESIGN COMPLETENESS		/	,
	MORE COMPLETE THAN NEEDED	.7595		!
	ADEQUATE FOR LEVEL OF ESTIMATE	1.00		1.00
	LESS COMPLETS THAN NEEDED	1.05 - 1.10		*
	OTHER:	.75 - 1.10		
9.				
	EQUIPMENT RENTAL	1.00 - 1.05		
	MOBILIZE/DEMOBILIZE	1.00 - 1.10		
	SCAFFOLDING	1.05 - 1.15		
	QUALITY CONTROL	1.10 - 1.20		1.10
	MATE HANDLING/WAREHOUSING	1.10 - 1.25		
	CLEAN-UP	1.10 - 1.30		
	OTHER:	1.00 - 1.30		
- :	CONSTRUCTION SITE CONDITIONS +			
	UNCESTRUCTED AREA	.95 - ,EE		
	LIMITED OBSTRUCTION	.95 - 1.00		1.00
	CBSTRUCTED AREA	1.00 - 1.10		
	OTHER:	.85 - 1.10		
J.	METHOD OF ACCOMPLISHMENT/MARKET CONDITIONS			
	FIXED PRICE (FP)	.85 - 1.15		1.00
	MAINTENAUCE	.95 - 1.35		
	CORT PLUS FIXED RES (OPFF)	1.00 - 1.21		
	OTHER:	.25 - 1.20		

MULTIPLIER A: 1.00 \times B: 1.10 \times C: 1.00 \times D: 1.00 \times MIDPOINT 25 % =27.50 % SONTINGENCY

^{*} IGNETRUCTION BITE CONDITIONS: - UNCESTRUCTED-MINIMAL U/S UTILITIES, UNCONGESTED AREA, NO CONTAMINATION, NO PROCESSE - LIMITED OBSTRUCTION-ONE OF THE ABOVE ITEMS NOT TRUE - IBSTRUCTED-TWO OR MORE OF THE ABOVE ITEMS NOT TRUE

• •	-	9	/3 / 43\
•	-		(2 424
	4	SITEMORK*	\ \ <u>\</u> '
			·-

Α.	DESIGN COMPLETENESS		
	MORE COMPLETE THAN NEEDED	.70 ~ .95	
	ADEQUATE FOR LEVEL OF ESTIMATE	.90 - 1.00	
	LESS COMPLETE THAN NEEDED	, 95 - 1,05	1:03
	OTHER:	.70 - 1.05	
В.	DENSTRUCTION COMPLEXITY		
	IMPROVEMENTS TO LAND	.8095	
	SARTHWORK	.90 - 1.00	1.00
	REMOVALS - COLD	.90 - 1.05	
	UTILITIES - ABOVE GROUND	.95 - 1.10	
	CAIBEONS	1.00 - 1.15	
	REMOMALS - ASSESTOS	1.10 - 1.20	
	UTILITIES - SELOW GROUND	1.15 - 1.30	
	REMOVALS - HOT	1.20 - 1.50	
	STHER:	.50 - 1. 5 0	
ī.	CONSTRUCTION SITE CONSTITUES *		
	UNCBSTRUCTED AREA	.8395	
	LIMITED DESTRUCTION	.95 - 1.00	1.00
	OBSTRUCTED AREA	1.00 - 1.10	
	OTHER:	.85 - 1.10	
D.	MSTHOD OF ACCOMPLIBHMENT/MARKET CONDITIONS		
	FIXEL PRICE (FP)	.85 - 1.15	i. Ju
	MAINTENANCE '	.95 + 1.3Š	
	SOBT PLUS FIXED FEE (OPFF)	1.00 - 1.20	
	CTHER:	.85 - 1.20	

MULTIPLIER A: 1.05 \times B: 1.00 \times C: 1.00 \times D: 1.00 \times MIDPCINT 25 % =26.25 % CONTINGENCY

^{*} CONSTRUCTION SITE CONDITIONS:
UNCOSTRUCTED-MINIMAL U/G UTILITIES, UNCONGESTED AREA, NO CONTAMINATION, NO PROCESSES
LIMITED OBSTRUCTION-ONE OF THE ABOVE ITEMS NOT TRUE
COSTRUCTED-TWO OR MORE OF THE ABOVE ITEMS NOT TRUE